
Note: Where the wall is constructed of Lath and Plaster, the MDF Fire Resistant board is to be mechanically fixed to the timber battens and not the



SECTION A

Do not scale this drawing.

All dimensions to be checked on site prior to commencement or manufacture.

## CONTROLLED DOCUMENT

## PLANNING ISSUE

ĒΕ	ěγ	-				
_	Rev Date	-				
	Ву	-				
	웆	-				
	By Chk Comment	1				

25 YEARS OF BRINGING IDEAS TO LIF

FRANKHAM

Frankham Consultancy Group Limited
Oakfield House 35 Perrymount Road
Haywards Heath RH16 3BW
T01444 444900 £01444 455642
Eenquire@frankham.com
www.frankham.com

East Sussex County Council

Project Title Robertsbridge Youth Centre East Sussex, 58 The Grove Robertsbridge Sussex, TN32 5AP

General Repairs Fire Resistant MDF Board Fixing Detail

File Ref:	Designed by: BT	BT	Drawn by:
	Checked by: BM	1:50 @ A3	Scale:
	Approved by:	03/02/2010	Date:

Drawing No.	Rev.
520970-B-04	1