



F2 Utilities Assessment

BONNERS CEP SCHOOL, MARESFIELD - NEW CHILDRENS CENTRE

MAIN UTILITIES STATEMENT

Site surveys have been undertaken at the existing school premises and it is considered that there is insufficient capacity on the existing electricity utility service to serve the new building. The 'old' water service to the existing school is considered to be unsuitable to serve the new building.

A new electrical utility connection is therefore proposed, together with a new dedicated water main taken direct from the existing metered supply at the site boundary.

WP/862(BON)

February 18th 2010