

ROBERTSBRIDGE YOUTH CENTRE

GENERAL REPAIRS LISTED BUILDING CONSENT APPLICATION

PHOTO SCHEDULE

11th December 2009



FRANKHAM

Robertsbridge Youth Centre – Photo Schedule



Chimney Pots

Chimney Pots

Photo 1 – Front (South) elevation Chimney Pots

Robertsbridge Youth Centre – Photo Schedule



Damaged Chimney Pot

Chimney Pots

Photo 2 – Side (East) elevation Chimney Pots


Robertsbridge Youth Centre – Photo Schedule



Chimney pots to West elevation

Photo 3 – Side (West) elevation Chimney Pots


Robertsbridge Youth Centre – Photo Schedule



Wall in Pool Room to be dry lined with Fire retardant MDF

Photo 4 – Pool Room Wall

Robertsbridge Youth Centre – Photo Schedule



Damaged wall to Pool Room to be lined with fire retardant MDF

Photo 5 – Pool Room Wall

Robertsbridge Youth Centre – Photo Schedule



Damaged ceiling to Pool Room to be repaired

Photo 6 – Pool Room Ceiling